

1641x3

PREPARATORY INSPECTION MEETING

Time Series Sampling

Conducted by/Company:

William E. Wright / Brien & Gere

Date: 28 Mar 00

Project Name:

Solutia Sargent Area

Task:

Time-series sampling

1. Scheduled Work:

see below

2. Equipment, Procedures, Personnel:

3. Ref. To App. Sec. of FSP/HASP:

FSP # 5.12

HASP # 2.6

4. Issues that could arise and how to resolve:

see below

5. Solutia comments:

" "

6. EPA comments:

" "

① Time-series GW sampling on Judith Ln. & Walnut St.

② Equip: push probe rig, MicroWell™, sampling equipment, Mod. D PPE

Procedures: install one MicroWell™ at each shallow res. GW samp. location on Judith Ln. & Walnut St. (2 wells total); screened well interval at zone of highest detected constituent concentrations (~40 Fg); GW samples to be collected over 24 hr w/ continuous purging, at 0 hr, 12 hr & 24 hr; use peristaltic pump & poly tubing, set GW flow as high as possible without drying up well;

temp., pH, conductivity, turbidity measurements recorded periodically; MicroWells pulled, holes

Personnel: Harris → installation & removal of MicroWells™

filled w/ bentonite after sampling

DBG → purging & sampling

③ see above

④ well dries up → resolve by lowering flow & waiting for recharge

- vandalism → resolve by attending wells during purging & sampling and capping after installation

⑤ - turning off flow not desired to collect VOC's samples

⑥ none

ATTENDANCE:

EMPLOYEE NAME (print)

EMPLOYEE SIGNATURE

COMPANY

Jim Harris

Jim Harris

Harris & Gere

Ron Labbe Jr.

Ron Labbe Jr.

Catholic Police

Nick Jenkins

Nick Jenkins

DBG

Kirk Perry

Kirk Perry

Solutia

Don Lafferty

Don Lafferty

MARRICK

cc: K. Perry 28 Mar 00

T. Gougeon @ 1845

IF ADDITIONAL SPACE IS REQUIRED
RECORD ON REVERSE SIDE

William E. Wright / William E. Wright
PRINTED NAME/SIGNATURE OF PREPARER

28 Mar 00

DATE